

21 ST STREET NORTH CORRIDOR REVITALIZATION PLAN

CITY OF WICHITA, KANSAS

MAP II.6: EXISTING ENVIRONMENTAL CONDITIONS

LEGEND

Study Area Boundary

- Violations/Spills
- Institutional Measures
- No Confirmed Contamination
- Potential/ Confirmed GW/ Soil Contamination
- Monitoring Status
- Active Status
- Sites within 1 Mile of Study Area
- Hold Status
- 29th & Grove Plume
- Possible Pipe Leak
- Tank Site
- Fuel Oil
- Auto Salvage
- Junk Yard

